

- CD1.2 Change BS 5758 to BS 5756 (3 occurrences)
- CD1.4 The value of  $G_{\text{mean}}$  for GL24h should be 720, not 660 N/mm<sup>2</sup>  
The value of  $G_{\text{mean}}$  for GL24c should be 590, not 660 N/mm<sup>2</sup>  
The value of  $G_{\text{mean}}$  for GL36c should be 850, not 860 N/mm<sup>2</sup>  
Footnote b should be deleted together with the superscripted reference to it  
Footnote c should be reassigned as footnote b
- CD2.1.1 Second paragraph insert ‘per shear plane’ after ‘The spreadsheets give the load-carrying capacity’
- CD2.4 Insert ‘per shear plane’ in headings of active spreadsheets for 3-member joints after ‘Lateral design loads’ (this applies to 10 of the 13 tables)
- CD2.5 Insert ‘per shear plane’ in headings of active spreadsheets for 3-member joints after ‘Lateral design loads’ (this applies to 9 of the 12 tables)